



EMAIL: sales@bathroomsareus.com.au
WEB: www.bathroomsareus.com.au

OFFICE: 15/115 Robinson Rd East
Geebung QLD 4034
MAILING: P.O. Box 112
Wavell Heights QLD 4012
PHONE: 07 3216 5855
FAX: 07 3216 5366
ABN 33 568 182 859
QBCC No. 49737



Dear Client

SHOWER REPAIR

With reference to your enquiry regarding your property, we would anticipate your shower repair to be in the region of \$4,000.00 - \$5,000.00. This would include a full strip out of 2.1 walls of shower area plus shower floor, re-line shower area with villaboard, full wet seal of shower area with hebel hob, walls and floor, new combination and tapware or mixer, a re-tile of shower area walls of approximately 6 sq.metres and new bedded floor tiles in shower area of 1 sq.metre, new standard framed pivot door and return side panel in clear glass and polished silver framing.

Any water damage that has caused structural problems to stud work or any external walls would be an extra and would need to be assessed on site after removal of existing shower enclosure and walls.

Please use this as a guide only and if we are around the right budget you are looking for, please give us a call and we can organise a site visit to provide you with a detailed quote.

With thanks

Regards

Randall Morrison

Bathroom Designer