



EMAIL: sales@bathroomsareus.com.au
WEB: www.bathroomsareus.com.au

OFFICE: 15/115 Robinson Rd East
Geebung QLD 4034
MAILING: P.O. Box 112
Wavell Heights QLD 4012
PHONE: 07 3216 5855
FAX: 07 3216 5366
ABN 33 568 182 859
QBCC No. 49737



Quote Created: May 2021

Valid Until: December 2021

Dear Client,

RE: SHOWER REPAIR for Cavity walls with timber floor or concrete floor

With reference to your enquiry your property, we would anticipate your shower repair to be in the region of \$5,500.00 to \$6,500.00. (Subject to location). This pricing is exclusive of GST.

Description of work:

- This would include a full strip out of shower wall sheetings (Not including Asbestos sheeting)
- Plus 1.0 sq/m shower floor on timber or concrete floor.
- Re-line shower area with 6mm Hardie Villaboard
- Full wet seal of shower area and hob including six and half year warranty on waterproofing with form 16.
- Re-tile of shower area walls of approximately 6 sq.metres and new bedded floor tiles in shower area of 1 sq.metre with smart tile waste (Excluded purchase of wall and floor tiles)
- Supply and install of 900 x 900 Semi- frameless shower screen with pivot door and 900mm return side panel in 6mm clear glass and polished silver frame.
- Full compulsory QBCC home warranty insurance up to \$6000.00 included at \$230.00

Products:

- 1 x Shower Rail in chrome up to \$235.00
- 1 x Shower mixer or tapware in chrome up to \$165.00,
- 1 x 100 x100 Smart tiled shower floor waste in chrome up to \$70.00,
- 1 x Semi-frameless 900 x 900 x 1950mm shower screen in clear glass with polished silver frame finish up to \$850.00.

Any water damage that has caused structural problems to floor or walls would be an extra and would need to be assessed on site after removal of existing shower enclosure and walls.

Please use this as a guide only. If we are around the budget you are looking at, please give us a call on 07 3216 5855 and we can organise a site visit.

With thanks,
Randall Morrison
Bathroom Designer